



SPECIFICATION SHEET

Black Rynolite Etching Primer

Product: 1030

Alkyd Rust-Inhibiting Etching Primer (Satin Sheen)

10/2019

DESCRIPTION:

Black Rynolite Etching Primer offers fast air drying, excellent adhesion, durability and easy application qualities. It is a complete ready to use primer that cuts through the typical thin layer of surface metal oxide and adheres well to the metal itself.

RECOMMENDED USES:

Black Rynolite Etching Primer is for use on non-ferrous metals such as aluminum and copper because of its built in etching ability. Also performs well on ferrous surfaces as a general purpose primer.

THINNING: Thin if necessary with Farwest Toluol.

CLEAN-UP: Equipment and tools may be cleaned with Farwest Toluol or Farwest 615 Wash Thinner.

APPLICATION: Brush or spray.

SURFACE PREPARATION: Surface to be coated must be free of all loose dirt or scaling paint and any other foreign material. All loose rust scales should be removed either by wire brushing, light sandblasting or with Farwest 695 Rynolite Chemical Cleaner-Etcher.

COVERAGE: 300 sq. ft. per gallon at approximately 2.0 mils dry.

DRY TIME:

Dry to touch in 15 minutes. Tack free in 30 minutes. Recoat in 2 hours. Dries hard in 2 hours.

COLORS & TINTING: Black

VEHICLE TYPE: Alkyd Fortified, Natural Oils

WEIGHT PER GALLON: 9.85 pounds per gallon.

% SOLIDS: 36-38% by volume. 52-54% by weight.

FLASH: 50°F

V.O.C.: Maximum 538 grams per liter.

VISCOSITY: 60-65 k.u.

CAUTIONS:

CONTAINS PETROLEUM DISTILLATE: VAPOR HARMFUL. MAY AFFECT THE BRAIN OR NERVOUS SYSTEM CAUSING DIZZINESS, HEADACHE OR NAUSEA. CAUSES EYE, SKIN, NOSE AND THROAT IRRITATION. Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal.

PRECAUTIONS: Keep away from heat and flame. Prevent build-up of vapors by opening windows and doors to achieve cross ventilation.

USE ONLY WITH ADEQUATE VENTILATION.

CAUTIONS CONTINUED:

USE ONLY WITH ADEQUATE VENTILATION. Do not breathe vapors or spray mist. Ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness, or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH/MSHA approved) during and after application. Follow respirator manufacturer's directions for respirator use. Avoid contact with eyes, skin and clothing. Wash thoroughly after handling. Close container after each use.

KEEP OUT OF REACH OF CHILDREN.

First Aid: If swallowed, do not induce vomiting. Call physician immediately. If you experience difficulty breathing, leave area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately. In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention. For skin contact, wash thoroughly with soap and water.

SPECIAL INSTRUCTIONS:

IF SPILLED: Contain spilled materials and remove with inert absorbent. Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations.

DISPOSAL OF OILY RAGS: Rags and other waste materials soiled with this product may spontaneously catch fire if improperly discarded. Soak soiled rags and waste immediately after use in a water-filled, closed metal container.

In Case of Chemical Emergency call ChemTrec (24hr): 1-800-424-9300

Farwest Paint Mfg Co

4522 S 133rd St ~ Tukwila, WA ~ 98168

www.farwestpaint.com

T: (206) 244-8844 F: (206) 246-7691